# **T-Gen2 Firmware Updates**

This bulletin provides details of a new version of T-Gen2 firmware V2.5 which has been released, and the procedure for upgrading existing T-Gen2 firmware.

# **T-Gen2 V2.5 Features**

T-Gen2 V2.5 firmware includes the following improvements:

- When a general purpose input is configured for paging, it responds quickly to a user pressing the button on the paging microphone, to remove any noticeable delay to speech being output from the T-Gen2.
- If the T-Gen2 is powered by an external 24V supply which cannot provide the required maximum load current there is a small probability the T-Gen2's amplifier maybe damaged due to the +24V supply voltage continuously collapsing and recovering every few seconds (e.g. supply voltage collapses each time the T-Gen2 attempts to play the Evac tone). V2.5 software adds protection against this situation. Note this condition is unlikely, but might be encountered if a T-Gen2 system is powered from a power supply that is not rated to provide the required current.

# T-Gen2 V2.4 Features

T-Gen2 V2.4 firmware supports both the earlier PCB and the latest issue E PCB. Note the issue E PCB uses a different brand of OLED display.

# T-Gen2 V2.3 Features

T-Gen2 V2.3 firmware includes the following corrections:

- Fixes a problem that could have resulted in the T-Gen2 not playing tones or sounds.
- Improved read performance of sound files on some external SD cards.
- Improved file handling when opening sound files for playback.

These corrections are included in V2.3 which was released to production of new T-Gen2 in October 2020.

Existing T-Gen2 with V2.0 through V2.2 firmware should be upgraded to this version.

Existing V1.xx units do not have these specific problems.

## T-Gen2 V2.2 Features

T-Gen2 V2.2 firmware includes the following corrections:

- A T-Gen2 supervising two branches of speaker wiring will now detect a fault on one of the branches. Commission testing will have identified this problem on affected sites.
- The strobe output will always turn off when the strobe is no longer required. Earlier versions could leave the strobe output in the last known state (either on or off).

These are included in V2.2 which was released to production of new T-Gen2 in March 2020.

Existing units with V2.1 or earlier should be upgraded to this version.

# **T-Gen2 V2.1 Features**

T-Gen2 V2.1 firmware fixes an issue in V2.0 where a chime signal selected to play when a digital input triggers paging on Audio Input 1 or 2, is played for only the first activation after power-up. From then on, the chime is not played on activation of the paging input.

This is fixed in V2.1 which was released to production of new T-Gen2 in April 2019.

Existing units with V2.0 requiring the paging chime signal can be upgraded as described below.

## T-Gen2 V2.0 Features

T-Gen2 V2.0 is a significant upgrade and releases many new features.

- Grade 2 operation as per AS 4428.16 with most optional functions available.
- Up to 20 zones of indication and control.
- User interface operation complies with AS 4428.16.
- Slave T-Gen2 and 100V Switching Module operation supports 3 simultaneous audio channels.
- 14A PSE and Grade 2 User Interface QBus modules supported.
- High Level Interface (HLI) with Vigilant MX1/MX4428/F3200 using RZDU allows transfer of 32 alarm signals and fault state.
- High Level Interface (HLI) with Simplex 4100ESi internal 4100Comms allows transfer of 32 alarm signals and fault states.
- 100V Switching Module and T-Gen2 100V outputs assignable to areas for nonemergency use and zones for emergency use.
- Slave T-Gen2 100V output and Strobe output separately assignable to an area and zone.
- Non-emergency Audio inputs and User functions mappable to each area.
- Cascade table defines phased evacuation different operation per alarm trigger.
- High priority functions (e.g., lockdown) available.
- Time-tagged Event History capture and display on OLED and stored on MicroSD card if present.
- Diagnostics display of voltages and currents from 14A PSE.
- T-Gen2 in Slave Mode allow digital inputs to be assigned functions like zone alarm trigger, play message.
- Improved sound level from front panel microphone (Speech and Paging).
- Improved fault detection/resilience on 100V and Strobe outputs.
- New default configurations including a Grade 2 choice.

## Compatibility

SmartConfig V2.8 or higher is required for T-Gen2 V2.0 (or later) for preparation of sitespecific configurations. This includes new defaults and the programming choices for the new features. It also supports the existing T-Gen2 units with V1.xx firmware.

Existing T-Gen2 units with V1.xx firmware can be upgraded to V2.00 (or later) by using the upgrade process below. The existing configuration (default or site-specific) will be supported, but preparing and installing a new configuration based on a V2 template is recommended as this will allow use of the new features.

In a system with Slave T-Gen2 it is necessary for the master and all slaves to have the same firmware (i.e., all have V2.xx or the earlier V1.xx), as a V2.xx T-Gen2 cannot be used with V1.xx T-Gen2. Thus it may be necessary to upgrade an existing system or T-Gen2 to V2.00 (or later) if a Slave T-Gen2 is being added.

# Check T-Gen2 Firmware Version

It is possible to determine the installed firmware on a working T-Gen2 as follows:

- 1. Use the NEXT button to step through the T-Gen2 OLED menu until the Software option is shown, then press the SELECT button.
- 2. A Firmware option will be shown. Press the SELECT button again.
- 3. The OLED will display the Master T-Gen2 firmware version and CRC.
- 4. Press BACK three times to return to the base display.

## **Obtaining T-Gen2 Firmware & SmartConfig Lite V2.8**

The new T-Gen2 firmware (SF0534) and SmartConfig Lite V2.8 (SF0324) can be obtained from the Fireplace:

http://vigilant-fire.com.au.

Click on **Resources | Downloads ANZ** and then **Goto T-Gen2.** Right click on **SF0534** for the T-Gen2 firmware or **SF0323** for SmartConfig Lite and save the file on your PC. SF0534 is a zip file that contains the necessary file for updating or programming the T-Gen2. Instructions for installing SmartConfig Lite can be found in the latest version of Product Bulletin PBG0209.

# **Upgrading Existing T-Gen2 Firmware**

1. A PC running Windows with a free USB port and a micro USB cable to connect to the T-Gen2 are required.

#### WARNING:

It is highly recommended to use a laptop PC running off its battery (i.e. not plugged into the mains) when using the USB port on the T-Gen, and connecting the USB lead to the T-Gen with the T-Gen turned off. This minimises the chance of damaging the USB port on the T-Gen due to the Earth monitoring which typically results in the 0V on the T-GEN being at +12V relative to the PC.

- 2. With the power to the T-Gen turned off connect the micro USB cable to the PC and T-Gen2. Turn on the power to the T-GEN and verify the TGEN2 BOOT disk is available on the computer (use Explorer to show the available disk drives).
- Activate the Boot Mode on the T-Gen2: While holding down the BACK and NEXT button, power up the T-Gen2 (or use the Diagnostics | ReBoot T-Gen2 command). A message 'T-Gen2 Boot Mode' and a 120 seconds count down timer will be shown.

Computer +			• 49 Search Computer		8
Organize      System properties	Uninstall or change a program	Map network drive	Open Control Panel		0
Favorites     Desktop     Downloads     OneDrive     Downloads	OSDisk (C:) 127 GB free of 231 GB activity Removable Storage (2)	]			
Fire Detection Sh File Detection Sh File netgate Projects VIGDOCS VIGDOCS	DVD RW Drive (D:) ork Location (5)	TGEN2 BC	DOT (E:) te of 0.98 MB		
	around\$ 0\natche3600001\(G)	interes (A)	orche3600001) (Hz)		

4. Open the newly added TGEN2 BOOT drive and copy the existing firmware .bin file to a backup folder on your computer. This may be used for a firmware roll-back if required.

Comput	ter 🕨 TGEN2 BOOT (E:)		✓ ✓ Search TGEN	2 BOOT (E:)	
Organize 👻 Share wi	th <del>▼</del> Burn New folder				
☆ Favorites	Name	Date modified	Туре	Size	
📃 Desktop	SF0534 TGEN2_V100.bin	7/12/2017 9:38 a.m.	BIN File	254 KB	
📜 Downloads					
la OneDrive					
🔚 Recent Places					
Fire Detection Sh					
🖳 netgate					

- 5. Delete this .bin file from the TGEN2 BOOT drive. There should be no files left and the T-Gen2 OLED display will show 'No Valid APP'.
- 6. Copy the new .bin file to the empty T-Gen2 drive. Once completed, the T-Gen2 will automatically reboot using the new firmware. If an attempt is made to copy an invalid firmware file to the T-Gen2 the copy process will fail, and the drive will be closed.

*Note:* The T-Gen2 boot mode will end when the timer expires, so these steps need to be completed in that time. The T-Gen2 will restart the existing application if one is present. Repeat the process if the timer expires before completing the installation of the new firmware. To roll-back or undo the upgrade, follow the same instructions but use the backup .bin file made in step 4.

The SmartConfig Lite User Manual LT0345 contains information on updating and programming the T-Gen2 and includes steps to erase the firmware if the TGEN2 BOOT USB drive is not presented to the PC when the USB cable is plugged in.

#### **Resources**

The SmartConfig Lite User Manual LT0345, used for updating and programming the T-Gen2, is included with SmartConfig Lite, or can be obtained from the Fireplace website.

#### http://vigilant-fire.com.au.

Click on **Resources | Manuals ANZ** and then **T-Gen2 60W and 120W** to see the LT0345 link.

# **Previous T-Gen2 Firmware Versions**

#### V1.12

This release addresses two specific issues with the following symptoms:

- The T-Gen2 may generate an amplifier fault when a long speaker cable is connected. The capacitance of the long cable causes the high frequency test signal generated by the T-Gen2 to be suppressed. The T-Gen2 amplifier supervision method considers this a fault and it is displayed on the OLED as "AMP Fault". The fault shows up 100 seconds after power-up of the T-Gen2 when the long cable is connected. Removing the long cable (leaving just the EOL) causes the fault to clear.
- 2) When using the PA microphone, the volume of the speech generated via the loudspeakers is low.

It is suggested any T-Gen2 with V1.00 firmware exhibiting these issues could be upgraded to V1.12. There is no impact to the existing configurations stored in the T-Gen2. However it is recommended an upgrade to V2.00 be made as this provides many new features.

#### V1.0

Original release for Grade 3 operation only.

## **Product Information**

For ordering, please contact Johnson Controls Customer Service in Melbourne on 1300 725 688 or <a href="mailto:fdp.customerservice.anz@jci.com">fdp.customerservice.anz@jci.com</a>

For application or sales enquiries, please contact your local Johnson Controls sales representative.

For technical support or technical training enquiries, contact Johnson Controls Technical Support Centre on 1300 552 559 in Australia or 09 635-0617 in New Zealand.

Further information on the extensive range of fire detection products available from Johnson Controls is available on the **Fireplace** website at <u>http://vigilant-fire.com.au</u>.